



New Orleans: (504) 733-1808  
Houston: (713) 671-6061  
New York: (845) 548-5655  
California: (714) 994-3070

GeneralWorkProducts.com  
PalmerSafetyUS.com

## TESTING PROCEDURE




MADE IN BELGIUM BY  
**BEXCO**



### Testing Procedure for Hyper XII™

- Initial setting cycles: Cycling 10 times from 1% to 50% of spliced breaking strength
- Load to 50% of the MBL and hold for 30 minutes
- After 1% to break
- Pin diameter minimum 3X diameter of rope



Specifications are subject to change without notice. General Work Products makes no warranties to the use for a specific use or installation of products referred to, no guarantee of satisfactory results from reliance upon contained information or recommendations and disclaims all liability for resulting loss or damage. General Work Products recommends installing the herein specified products in accordance with ANSI A-10-11-1989 and OSHA 1926.502 or all applicable local, state or federal requirements. Correct installation is the sole responsibility of the user/installer.