




INSPECTION AND RETIREMENT CRITERIA





ACTION REQUIRED


- 1. Flex / loosen the rope
- 2. Push strand back into the rope



ACTION REQUIRED Cut and reterminate rope

VISUAL DAMAGE

ACTION REQUIRED



ACTION REQUIRED Cut and reterminate rope **VISUAL DAMAGE**

Transverse pressure: Local deformation, glazed surface

ACTION REQUIRED Cut and reterminate rope

VISUAL DAMAGE Cut yarns in different strands

ACTION REQUIRED

Cut and reterminate rope

VISUAL DAMAGE Burn damage: Dark coloration, melted spots

> **ACTION REQUIRED** Cut and reterminate rope